





WIRING DIAGRAM SYMBOLS



TRANSFORMER



MOTOR SWITCH POSTIONS



"COLOR CODE ABBREVIATIONS"

BL = BLUE	SL = SLATE
BR = BROWN	YEL = YELLOW
BLK = BLACK	WH = WHITE
GR = GREEN	MAR = MAROON
OR = ORANGE	PUR = PURPLE

EXAMPLE:

BL - WH = BLUE WITH A WHITE TRACER.
BL & WH = BLUE AND WHITE MOTTLED.

