

<p>IMPORTANT NOTE</p> <p>WHEN USING DRIVER BOARDS WITH PADS FOR SWITCH MATRIX SERIES RESISTORS R204 THRU R211 (EARLIER BOARDS), THOSE COMPONENTS MUST BE ZERO-OHM OR BE REPLACED WITH JUMPER WIRES.</p> <p>500-8A</p>	<p>IMPORTANT NOTE</p> <p>WHEN USING DRIVER BOARDS WITH PADS FOR SWITCH MATRIX SERIES RESISTORS R204 THRU R211 (EARLIER BOARDS), THOSE COMPONENTS MUST BE ZERO-OHM OR BE REPLACED WITH JUMPER WIRES.</p> <p>500-8A</p>	<p>IMPORTANT NOTE</p> <p>WHEN USING DRIVER BOARDS WITH PADS FOR SWITCH MATRIX SERIES RESISTORS R204 THRU R211 (EARLIER BOARDS), THOSE COMPONENTS MUST BE ZERO-OHM OR BE REPLACED WITH JUMPER WIRES.</p> <p>500-8A</p>
<p>IMPORTANT NOTE</p> <p>WHEN USING DRIVER BOARDS WITH PADS FOR SWITCH MATRIX SERIES RESISTORS R204 THRU R211 (EARLIER BOARDS), THOSE COMPONENTS MUST BE ZERO-OHM OR BE REPLACED WITH JUMPER WIRES.</p> <p>500-8A</p>	<p>IMPORTANT NOTE</p> <p>WHEN USING DRIVER BOARDS WITH PADS FOR SWITCH MATRIX SERIES RESISTORS R204 THRU R211 (EARLIER BOARDS), THOSE COMPONENTS MUST BE ZERO-OHM OR BE REPLACED WITH JUMPER WIRES.</p> <p>500-8A</p>	<p>IMPORTANT NOTE</p> <p>WHEN USING DRIVER BOARDS WITH PADS FOR SWITCH MATRIX SERIES RESISTORS R204 THRU R211 (EARLIER BOARDS), THOSE COMPONENTS MUST BE ZERO-OHM OR BE REPLACED WITH JUMPER WIRES.</p> <p>500-8A</p>
<p>IMPORTANT NOTE</p> <p>WHEN USING DRIVER BOARDS WITH PADS FOR SWITCH MATRIX SERIES RESISTORS R204 THRU R211 (EARLIER BOARDS), THOSE COMPONENTS MUST BE ZERO-OHM OR BE REPLACED WITH JUMPER WIRES.</p> <p>500-8A</p>	<p>IMPORTANT NOTE</p> <p>WHEN USING DRIVER BOARDS WITH PADS FOR SWITCH MATRIX SERIES RESISTORS R204 THRU R211 (EARLIER BOARDS), THOSE COMPONENTS MUST BE ZERO-OHM OR BE REPLACED WITH JUMPER WIRES.</p> <p>500-8A</p>	<p>IMPORTANT NOTE</p> <p>WHEN USING DRIVER BOARDS WITH PADS FOR SWITCH MATRIX SERIES RESISTORS R204 THRU R211 (EARLIER BOARDS), THOSE COMPONENTS MUST BE ZERO-OHM OR BE REPLACED WITH JUMPER WIRES.</p> <p>500-8A</p>

Fonts used: Tremolo
Card size: 50x59mm

Cards status:
Card 500-8 is confirmed, but is later replaced by 500-8A because it had wrong information about the resistor jumpers. Card 500-8 is replaced by 500-8A.
Card 500-8A is confirmed. (correct jumper information).
A similar card is STD-A714.
If you have any other information about these cards, please send a readable picture or scan to me.

Enjoy and have fun,
Peter
www.inkochnito.nl
If you like my work, please send me a donation via PayPal.

