

FOR 30VAC CIRCUIT	8A SLO-BLO →	FOR 30VAC CIRCUIT	8A SLO-BLO →
FOR 13VAC CIRCUIT	8A SLO-BLO →	FOR 13VAC CIRCUIT	8A SLO-BLO →
WARNING: <u>DO NOT</u> OVER FUSE ALL FUSES HAVE 250V RATING <i>PART #820-6075-00</i>		WARNING: <u>DO NOT</u> OVER FUSE ALL FUSES HAVE 250V RATING <i>PART #820-6075-00</i>	
FOR 30VAC CIRCUIT	8A SLO-BLO →	FOR 30VAC CIRCUIT	8A SLO-BLO →
FOR 13VAC CIRCUIT	8A SLO-BLO →	FOR 13VAC CIRCUIT	8A SLO-BLO →
WARNING: <u>DO NOT</u> OVER FUSE ALL FUSES HAVE 250V RATING <i>PART #820-6075-00</i>		WARNING: <u>DO NOT</u> OVER FUSE ALL FUSES HAVE 250V RATING <i>PART #820-6075-00</i>	
FOR 30VAC CIRCUIT	8A SLO-BLO →	FOR 30VAC CIRCUIT	8A SLO-BLO →
FOR 13VAC CIRCUIT	8A SLO-BLO →	FOR 13VAC CIRCUIT	8A SLO-BLO →
WARNING: <u>DO NOT</u> OVER FUSE ALL FUSES HAVE 250V RATING <i>PART #820-6075-00</i>		WARNING: <u>DO NOT</u> OVER FUSE ALL FUSES HAVE 250V RATING <i>PART #820-6075-00</i>	

Size: 64x64mm
Fonts used: Courier Prime

Cards status:

Rectifiers fuse label 820-6075-00 confirmed.

If you have any other information about these cards, please send a readable picture or scan to me.

Enjoy and have fun,
Peter

www.inkochnito.nl

If you like my work, please send me a donation via Paypal.