

<p>WARNING: <u>DO NOT OVER FUSE</u></p> <div> <div>F1</div> <div>F2</div> <div>7A SLO - BLO</div> <div>7A SLO - BLO</div> </div> <div> <div>.5A SLO - BLO</div> <div>8A SLO - BLO</div> <div>4A SLO - BLO</div> <div>5A SLO - BLO</div> </div> <div>F7</div> <div>F4</div> <div>F5</div> <div>F6</div> <p>ALL FUSES HAVE 250V RATING #820-6095-00</p>	<p>WARNING: <u>DO NOT OVER FUSE</u></p> <div> <div>F1</div> <div>F2</div> <div>7A SLO - BLO</div> <div>7A SLO - BLO</div> </div> <div> <div>.5A SLO - BLO</div> <div>8A SLO - BLO</div> <div>4A SLO - BLO</div> <div>5A SLO - BLO</div> </div> <div>F7</div> <div>F4</div> <div>F5</div> <div>F6</div> <p>ALL FUSES HAVE 250V RATING #820-6095-00</p>	<p>WARNING: <u>DO NOT OVER FUSE</u></p> <div> <div>F1</div> <div>F2</div> <div>7A SLO - BLO</div> <div>7A SLO - BLO</div> </div> <div> <div>.5A SLO - BLO</div> <div>8A SLO - BLO</div> <div>4A SLO - BLO</div> <div>5A SLO - BLO</div> </div> <div>F7</div> <div>F4</div> <div>F5</div> <div>F6</div> <p>ALL FUSES HAVE 250V RATING #820-6095-00</p>
<p>WARNING: <u>DO NOT OVER FUSE</u></p> <div> <div>F1</div> <div>F2</div> <div>7A SLO - BLO</div> <div>7A SLO - BLO</div> </div> <div> <div>$\frac{1}{2}$A SLO - BLO</div> <div>8A SLO - BLO</div> <div>4A SLO - BLO</div> <div>5A SLO - BLO</div> </div> <div>F7</div> <div>F4</div> <div>F5</div> <div>F6</div> <p>ALL FUSES HAVE 250V RATING #820-6095-00</p>	<p>WARNING: <u>DO NOT OVER FUSE</u></p> <div> <div>F1</div> <div>F2</div> <div>7A SLO - BLO</div> <div>7A SLO - BLO</div> </div> <div> <div>$\frac{1}{2}$A SLO - BLO</div> <div>8A SLO - BLO</div> <div>4A SLO - BLO</div> <div>5A SLO - BLO</div> </div> <div>F7</div> <div>F4</div> <div>F5</div> <div>F6</div> <p>ALL FUSES HAVE 250V RATING #820-6095-00</p>	<p>WARNING: <u>DO NOT OVER FUSE</u></p> <div> <div>F1</div> <div>F2</div> <div>7A SLO - BLO</div> <div>7A SLO - BLO</div> </div> <div> <div>$\frac{1}{2}$A SLO - BLO</div> <div>8A SLO - BLO</div> <div>4A SLO - BLO</div> <div>5A SLO - BLO</div> </div> <div>F7</div> <div>F4</div> <div>F5</div> <div>F6</div> <p>ALL FUSES HAVE 250V RATING #820-6095-00</p>

Fonts used: NudMotoyaExMincho-W3-90msp-RKSJ, NudMotoyaExMincho-W2b-90msp-RKS

Cards status:

Power Supply fuse label 820-6095-00 confirmed.

The top labels are like the original.

On the bottom label I've changed the F7 fuse rating from 0.5A to $\frac{1}{2}$ A, to avoid reading this mistakenly as 5A.

If you have any other information about these cards, please send a readable picture or scan to me.

Enjoy and have fun,

Peter

www.inkochnito.nl

If you like my work, please send me a donation via PayPal.